

Status	Date	Parish / Town Council	Contact Name and telephone number	Email Address	Location	Application Details (From Form)	Type of Scheme	Officer comments	Amount applied for	Revenue Amount awarded
Amber	20/9/22	Brompton Regis Parish Council	Sarah Buchanan (clerk) 01984 641706	brpcclerk@gmail.com	The road between Bessom Bridge and Rugglands the road is recurrently and seriously flooded, blocking the main communication route through the parish. Reported many times to the Highways Authority	The landowner has cleared the drains repeatedly and reported to the HA. He believes the flooding is caused by the pipes under the road being inadequate for the amount of water. One length of pipe needs to be increased to 12" diameter and the second pipe brings together a 6 inch and a 9 inch pipe, blockages occur at the join, and this length should be replaced with a 12 inch diameter pipe.	Drainage	This is a sizeable project but the work could be delivered in this financial year if the budget was available and a local contractor was employed. K Bridgwater / P Keal have knowledge on this. Some ongoing ditch maintenance also needed from neighbouring landowner.		
Amber	7/10/22	Brompton Regis Parish Council	Sarah Buchanan (clerk) 01984 641706	brpcclerk@gmail.com	Two roads that flood regularly. Could these be routinely maintained as part of a jetting scheme? - Blagdon Lane near the chicken sheds - Eastcott Lane (though this is also possibly related to a broken pipe between the drains).	Jetting required and more regular cyclical maintenance.	Drainage	The outfall ditch on the side of the road would need to be cleared before jetting can take place to provide an outfall. (Eastcott Lane has a broken pipe that would need to be picked up under BAU). The lane has been jetted and some grips cleared recently, so the main issue is the broken pipe.		
Amber	14/9/22	Exton Parish Council	Andrew Moore (Parish Clerk) 01984 641539	clerk@extonparishcouncil.co.uk	C200 Heathpoult Cross to Machine Cross on the A396	Regular flooding on this fast stretch of road during heavy rain. Drainage ditches cannot cope with the volume of water	Drainage	One side of the road has cabling from statutory undertakers (BT) so this prohibits/hinders work in this area. The drainage ditches on either side could be cleared by a local farmer with agricultural machinery if necessary. Some of this work is due to be addressed imminently under Business as Usual maintenance.		
Amber	1/11/22	Withypool and Hawkridge Parish Council	Rebecca Tomalin, Clerk and Responsible Financial Officer (01643 831638)	withypoolhawkridgeparishclerk@gmail.com	Colland Cross to West Hollowcombe, Colland Cross to Slade Bridge - Top 150m.	The drains and gullies along this stretch of road have not been cleared out properly for several years. Prolonged periods of rain create a river along this road which can run down into the village and cause flooding	Jetting / Gully Emptying	The ditches on the sides of the roads may also need to be cleared prior to work being undertaken. - Comprehensive maps now provided. The drainage pipes in Hawkridge are very old and there may be some issues with conventional jetting.		
Amber	1/11/22	Withypool and Hawkridge Parish Council	Rebecca Tomalin, Clerk and Responsible Financial Officer (01643 831638)	withypoolhawkridgeparishclerk@gmail.com	Drains on Blakeway, between Hawkridge & Withypool	The drains along Blakeway are often full of rubbish which causes a river to run down the road - more regular jetting would help alleviate some of these problems	Jetting	Need to establish the exact locations of the drains that need jetting - can be done as part of a collaborative programme with other parishes. Map provided.		

Green	1/9/22	Dulverton Town Council	Christine Dubery / Margaret Rawle	duberyc@aol.com	Jetting Requirements	Map received 14/11/22 with locations shown.	Jetting / Gully Emptying	Email with P.Keal and K.Bridgwater on 14/11/22 given preliminary approval and recognition of the fact that jetting would be beneficial. (Currently on a maintenance programme of every four years).		
Green	8/11/22	Brompton Regis Parish Council	Sarah Buchanan (clerk) 01984 641706	brpcclerk@gmail.com	Ruggs Hill towards Bessom Bridge, Brompton Regis	The Highways Steward has tried to clear drains and gullies on Ruggs Hill to stop water pouring down the road toward Bessom Bridge and pooling on the causeway. He believes the drains need jetting, and this is something we have asked for in the past and which i think was done about 4 or 5 years ago.	Jetting	Need to establish the exact locations of the drains that need jetting - can be done as part of a collaborative programme with other parishes. Gully emptying is being undertaken here as part of the general winter maintenance in November. If there is follow up work required it can be added to the list.		
	28/6/23	Skilgate Parish Council	Frances Nicholson (in the absence of a clerk)	skilgatemeeing@gmail.com	Between Frogwell Cross and Skilgate. What3Words Location Square.Things.Whisk	Highway Steward tried to clear but was unable to as blockage under the road. Requires Jetting to flush through the pipe.	Jetting	On main arterial route into the village. Complaint sent to Cllr Mike Rigby on Feb 22 with photograph.		
	28/6/23	Winsford Parish Council	Ian Brooks (Highways Warden)	ian.brooks97@gmail.com	Halse Lane, Winsford	150m past the Royal Oak, Winsford, opposite Hill House. The Highway Steward tried to clear this pipe under the road but it was beyond his capacity with rodding. He recommended jetting.	Jetting	Ongoing problem which has been reported on several occasions.		
	28/6/23	Winsford Parish Council	Ian Brooks (Highways Warden)	ian.brooks97@gmail.com	Exford Road to Winsford	All the drains (both sides) on a section of road from Larcombe Foot Bridge (sharp bend) towards Exford all the way to Oldrey Lane are blocked and full of detritus. Many drains are not visible and buried in the verge. Highway Steward will not undertake work here because traffic management required.	Jetting / Gully Emptying	Been reported ongoing since January 2023. Big job that will require more than a single operative. Gully cleansing definitely required. (Possible jetting).		
	28/6/23	Winsford Parish Council	Ian Brooks (Highways Warden)	ian.brooks97@gmail.com	Furzehill Lane (Opposite Quarre Monceaux House) to the top.	Routine Gully cleansing required and possibly jetting of 5 or 6 drains as ascending up Furzehill Lane.	Jetting / Gully Emptying	commnet box as above		
	28/6/23	Wootton Courtenay Parish Council	Roz Griffin (Parish Clerk) 01643 841245 / 07760238128	clerk.wcparishcouncil@gmail.com	SE side of the road from Tivington towards Headon Cross (dizziness.summaries.fortunes).	At the bottom of the track there is a drain that is blocked and needs jetting. Water is always running here alongside and across the road. During heavy rain water pools on the road and leads to flooding.	Jetting	Running water is causing the road to erode.		
	28/6/23	Wootton Courtenay Parish Council	Roz Griffin (Parish Clerk) 01643 841245 / 07760238128	clerk.wcparishcouncil@gmail.com	Road going down to Ford just above the corner on the West side (hopes.fabricates.admits).	There is a blocked drain here that requires jetting. Water accumulates on the road.	Jetting	Proceed as jetting		

	29/6/23	Timberscombe Parish Council	Timberscombe PC	timberscombepcclerk@gmail.com	All drains between Timberscombe Methodist Chapel and Allercott Farm, Timberscombe	Drains need to be cleared of leaves, etc. May also need jetting as water was coming up out of the drains in the heavy rain.	Jetting / Gully Emptying	Taken from HS Spreadsheet. Requested in Nov 22		
	30/6/23	Cutcombe Parish Council	Elizabeth Stitt (Cutcombe Parish Clerk and RFO). 07919001801	cutcombeclerk@gmail.com	Cutcombe and Wheddon Cross various	Jetting of drains requested.	Jetting	CLr Eric Norman will be able to let the operative know the locations. His number is 01643 841222. Map of locations to follow as soon as possible.		
	29/6/23	Dulverton Town Council	Frances Nicholson	duberyc@aol.com	Beech Tree is on the road from the top of Andrews Hill to the top of Windball Hill (sometimes called Northmoor Hill)	The double drain at the top of the drive of Old Shute at Beech Tree Cross is blocked, full of old soil and gravel and needs clearing.	Jetting	Taken from HS Schedule. HS advises jetting to release blockage in the outlet pipe further down the line.		
	30/6/23	Porlock Parish Council	Annie Dallaway Clerk/RFO	clerk@porlockparishcouncil.gov.uk	Hope Cottage Porlock. Gully under the path leading from the Central car park to the High Street.	Flooding has been occurring here in heavy rain and this would be a preventative measure.	Jetting / Gully Emptying	Proceed as jetting		
	30/6/23	Withypool and Hawkridge Parish Council	Rebecca Tomalin, Clerk and Responsible Financial Officer (01643 831638)	withypoolhawkridgeparishclerk@gmail.com	Sparrow Lane around Halsgrove Farm and House	Jetting of Drains on the approaches into Withypool – there is a steep hill whichever way Withypool is accessed. There is often a build up of debris in the gullies which causes a river to run down the road – more regular jetting would help alleviate some of these problems	Gully Emptying / Jetting	A map has been provided		
	30/6/23	Withypool and Hawkridge Parish Council	Rebecca Tomalin, Clerk and Responsible Financial Officer (01643 831638)	withypoolhawkridgeparishclerk@gmail.com	Kitridge Lane from Westerclose down to Olivers Cottage	Jetting of Drains on the approaches into Withypool – there is a steep hill whichever way Withypool is accessed. There is often a build up of debris in the gullies which causes a river to run down the road – more regular jetting would help alleviate some of these problems	Gully Emptying / Jetting	A map has been provided		
	30/6/23	Withypool and Hawkridge Parish Council	Rebecca Tomalin, Clerk and Responsible Financial Officer (01643 831638)	withypoolhawkridgeparishclerk@gmail.com	Quarry Head Lane, from Uppington Down to Pennycombe	Jetting of Drains on the approaches into Withypool – there is a steep hill whichever way Withypool is accessed. There is often a build up of debris in the gullies which causes a river to run down the road – more regular jetting would help alleviate some of these problems	Gully Emptying / Jetting	A map has been provided		
Green	3/8/23	Dulverton Town Council	Christine Dubery / Margaret Rawle	duberyc@aol.com	Various points in the Exmoor Division as indicated by the Devolved Funding Schedule.	Pay Dulverton Town Council to liaise with the preferred sub-contractor on site inspections prior to jetting / gully emptying. Estimated at 2 days work. £300 requested	Gully Emptying / Jetting	A sizeable amount of preparatory work has already been undertaken with a sub-contractor to assess the jetting / gully emptying in the schedule. This is a one off fee to Dulverton Town Council to cover these costs, and proceed with procurement.	£300.00	£300.00